

Services		Other services	
Water point status	Water quality	Friday mosque	Small mosque
Functional	Safe water	Market	Community center
Partially functional	Not safe water	Cemetery	
broken	Dried		
School and Health center			
School			
Health center			


Road and Boundaries

- District center
- Village boundary
- District boundary

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the IMPACT partners, associated, donors mentioned on this map

Data sources:
Admin Boundaries: AGCHO
Services and Village Boundaries: IMPACT
Coordinate System: GCS WGS 1984
Map Unit: Decimal Degree
Filename: IMPACT_AFG_Map_PARR_Badghis_Qala-e-Naw_Shamal Darya_PARRMapping_26APR2022_A3
Contact: geneva@impact-initiatives.org

Satellite Imagery:
Maxar (Geo1) from 23 April 2020
Copyright: 2020 Digital Glob
Source: ESRI



Water point status

- Functional
- Partially functional
- Broken

School and Health center

- School
- Health center

Services
Water quality

- Safe water
- Not safe water
- Dried

Other services



- Friday mosque
- Small mosque
- Market
- Community center
- Cemetery

Road & Boundaries

- District center
- Village boundary
- District boundary

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the IMPACT partners, associated, donors mentioned on this map.

Data sources:
Admin Boundaries: AGCHO
Services and Village Boundaries: IMPACT
Coordinate System: GCS WGS 1984
Map Unit: Decimal Degree
Filename: IMPACT_AFG_Map_PARR_Farah_Farah_Mohajer Abad_PARRMapping_26APR2022_A3
Contact: geneva@impact-initiatives.org
Satellite Imagery:
Maxar (Geo1) from 23 April 2020
Copyright: 2020 Digital Glob
Source: ESRI





<p>Water point status</p> <ul style="list-style-type: none"> Functional Partially functional broken <p>School and Health center</p> <ul style="list-style-type: none"> School Health center 	<p>Services</p> <p>Water quality</p> <ul style="list-style-type: none"> Safe water Not safe water Dried 	<p>Other services</p> <ul style="list-style-type: none"> Friday mosque Small mosque Market Community center Cemetery 	<p>Road and Boundaries</p> <ul style="list-style-type: none"> District center Village boundary District boundary
---	---	---	---

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the IMPACT partners, associated, donors mentioned on this map

Data sources:
Admin Boundaries: AGCHO
Services and Village Boundaries: IMPACT
Coordinate System: GCS WGS 1984
Map Unit: Decimal Degree
Filename: IMPACT_AFG_Map_PARR_Ghor_Feroz Koh_Amir Shansab Ghori_PARRMapping_26APR2022_A3
Contact: geneva@impact-initiatives.org

Satellite Imagery:
Maxar (Geo1) from 23 April 2020
Copyright: 2020 Digital Glob
Source: ESRI



Water point status

- Functional
- Partially functional
- Broken

School and Health center

- School
- Health center

Services
Water quality

- Safe water
- Not safe water
- Dried

Other services

- Friday mosque
- Small mosque
- Market
- Community center
- Cemetery


Road & Boundaries

- District center
- Village boundary
- District boundary

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the IMPACT partners, associated, donors mentioned on this map.

Data sources:
Admin Boundaries: AGCHO
Services and Village Boundaries: IMPACT
Coordinate System: GCS WGS 1984
Map Unit: Decimal Degree
Filename: IMPACT_AFG_Map_PARR_Herat_Guzara_Khatamul Anbiya_PARRMapping_26APR2022_A3
Contact: geneva@impact-initiatives.org

Satellite Imagery:
Maxar (Geo1) from 23 April 2020
Copyright: 2020 Digital Glob
Source: ESRI





<p>Water point status</p> <ul style="list-style-type: none"> Functional Partially functional broken <p>School and Health center</p> <ul style="list-style-type: none"> School Health center 	<p>Services</p> <p>Water quality</p> <ul style="list-style-type: none"> Safe water Not safe water Dried 	<p>Other services</p> <ul style="list-style-type: none"> Friday mosque Small mosque Market Community center Cemetery 	<p>Road and Boundaries</p> <ul style="list-style-type: none"> District center Village boundary District boundary
---	---	---	---

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the IMPACT partners, associated, donors mentioned on this map

Data sources:
Admin Boundaries: AGCHO
Services and Village Boundaries: IMPACT
Coordinate System: GCS WGS 1984
Map Unit: Decimal Degree
Filename: IMPACT_AFG_Map_PARR_Herat_Guzara_Rabat Saliman_PARRMapping_26APR2022_A3
Contact: geneva@impact-initiatives.org

Satellite Imagery:
Maxar (Geo1) from 23 April 2020
Copyright: 2020 Digital Glob
Source: ESRI



Water point status

- Functional
- Partially functional
- broken

School and Health center

- School
- Health center

Services
Water quality

- Safe water
- Not safe water
- Dried

Other services

- Friday mosque
- Small mosque
- Market
- Community center
- Cemetery

Road & Boundaries

- District center
- Village boundary
- District boundary

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the IMPACT partners, associated, donors mentioned on this map.

Data sources:
Admin Boundaries: AGCHO
Services and Village Boundaries: IMPACT
Coordinate System: GCS WGS 1984
Map Unit: Decimal Degree
Filename: IMPACT_AFG_Map_PARR_Herat_Guzara_Safid bar and Andisha_PARRMapping_26APR2022_A3
Contact: geneva@impact-initiatives.org

Satellite Imagery:
Maxar (Geo1) from 23 April 2020
Copyright: 2020 Digital Glob
Source: ESRI